



PANAMA MARITIME AUTHORITY
(AUTORIDAD MARÍTIMA DE PANAMÁ)
GENERAL DIRECTORATE OF MERCHANT MARINE
(DIRECCIÓN GENERAL DE MARINA MERCANTE)
DEPARTMENT OF CONTROL AND COMPLIANCE
(DEPARTAMENTO DE CONTROL Y CUMPLIMIENTO)

F-265
(DCCM)
V.00



MERCHANT MARINE CIRCULAR MMC-133

To: Ship-owners/Operators, Company Security Officers, Legal Representatives of Panamanian Flagged Vessels, Panamanian Merchant Marine Consulates and Recognized Organizations (ROs).

Subject: SHIP SECURITY ALERT SYSTEM (SSAS)

Reference: SOLAS 74', as amended, Regulation XI-2/6
Resolution MSC. 136 (76) December 11, 2002
Resolution n MSC. 147 (77) May 29, 2003
MSC/Circ. 1072 June 26, 2003
MSC/Circ. 1155 May 23, 2005
MSC.1/Circ.1190 May 30, 2006
Resolution J.D. No. 028-2003
Resolution No.106-107-DGMM October 9, 2017

1. The purpose of this Merchant Marine Circular is to update the instructions and procedures of the Ship Security Alert System (SSAS) according to SOLAS 74', as amended Chapter XI-2 Reg. 6, the IMO Resolution MSC 136(76) and Resolution **No.106-107-DGMM dated October 9th, 2017** ([Spanish version](#) or [English version](#)).
2. **From October 2017**, through the Resolution No.106-107-DGMM dated October 9th, 2017 this Administration communicated that all the Panamanian flagged vessels must to code the following email address threat@amp.gob.pa in their SSAS terminal (**as main account**), due to the fact that from **January 2018**, the annual SSAS TEST, will be received only through the SSAS Community electronic platform in the following link: <https://polestarglobal.force.com/SSAS/login>
3. For ships to enter the Panamanian registry as of January 1st, 2018, they must schedule the first **SSAS TEST** through the use of the new SSAS platform <https://polestarglobal.force.com/SSAS/login>, which must be verified by their RSO during the initial verification.
4. In those cases that the SSAS terminal has not been configured with the main email address threat@amp.gob.pa. This Administration granted a period until **August 31th, 2019** to make all the necessary arrangement to configure the SSAS terminal. The use of the following email authorizations@segumar.com is optional, if the company operator decides maintain both email address in their SSAS equipment.
5. Once the SSA terminal has been configured with the main email address threat@amp.gob.pa, the company operator shall request access to platform by email to the e-mail address: info@panama-ssas.com, and should submit copy of the last Declaration of Company Security Officer (**CSO**) endorsed by this Administration in order to receive an email from info@panama-ssas.com, with their access credentials and instructions for using the platform and be able to schedule the annual **SSAS TEST**.
6. Only one annual SSAS TEST is mandatory and must to schedule through the SSAS platform in the following link: <https://polestarglobal.force.com/SSAS/login>, in a period no longer than twelve (12) calendar months and can be

scheduled 24 hours in advance.

7. The confirmation message of the **annual SSAS TEST** only be confirmed through the SSAS platform and should be retained on board as evidence during the ISPS verification.
8. When the vessel changes name it will be necessary to schedule a new **SSAS TEST**, through the SSAS platform and must to follow the instruction:
 1. Request a CSO declaration with the new name through the E-Segumar platform at the following website link <http://certificates.amp.gob.pa/certificates>.
 2. Once the CSO declaration has been endorsed by this Administration, the company operator must send a copy directly to info@panama-ssas.com, in order that the new vessel name shall be updated in the SSAS platform.
 3. When the vessel name is reflected in the SSAS platform, the company operator must to schedule a new **SSAS TEST** through the platform, due to change of name.
 4. The RSO surveyor must to verify that the test was successful through the SSAS platform.
 5. When the test is performed for change of name it will be taken as the mandatory Annual SSAS Test.
9. When the vessel has been requested an SSAS Malfunction authorization it will be necessary to schedule a new **SSAS TEST**, through the SSAS platform in order to verify that the SSAS is working properly and the captain should send us the technical report at the following email: isps@amp.gob.pa
10. **From August 31th, 2019**, this Administration will only recognize the **SSAS TEST** that is made through the SSAS platform with the main email address threat@amp.gob.pa.
11. In case the information reflected in the SSAS platform does not match with the data of the vessel, please contact info@panama-ssas.com, in order to update the information.

SPECIAL REQUIREMENTS

The SSAS TEST messages must include the information described below. It is important that the information is encoded as it is being requested so that the SSAS TEST MESSAGE can be received.

1. TESTs must be sent via email, using ASCII, UTF-8 or ANSI encodings to the following address: threat@amp.gob.pa.

Name of vessel

The name of the vessel must be written in closed capital letters and should appear exactly as it is written in the Navigation Documents.

IMO number

It must contain 7 digits and may be preceded by the word "IMO".

Mobile Maritime Vessel Identifier

The MMSI must contain 9 digits, which cannot be separated by spaces, dashes or other characters.

Call Sign

It must contain between 4 and 7 digits and must appear exactly as it is written in the ship's registration patent. Do not use spaces, hyphens or other characters other than letters and numbers.

Date and time

The date can be represented in any of the following 3 formats:

- DD-MM-YYYY
- MM-DD-YYYY
- YYYY-MM-DD
- For which "DD" represents the day, "MM" represents the month and "YYYY" represents the year. The separators can be

slashes, points or dashes.

- The time can be represented in any of the following 2 formats:
- HH: MM
- HH: MM: SS
- For which "HH" is the hour expressed in 24-hour format, "MM" represents the minutes and "SS" represents the seconds.

All times must be submitted according to the Coordinated Universal Time (UTC).

Coordinates of the position of the vessel at the time of the SSAS test.

The coordinates can be expressed in degrees, minutes and seconds, degrees and decimals of minutes or in decimals of degrees and additional should indicate the hemisphere.

- Separators between grades, minutes and seconds can be:
 - The symbols for degrees, minutes and seconds (° '")
 - Two points (:)
 - Spaces
- The indicators of the hemispheres for the coordinates, must be expressed in the initial letter of the hemisphere and in English in capital letters:
 - "N" or "S" for latitude
 - "E" or "W" for length
 - The hemisphere can be placed before or after the position coordinates.

The heading and speed of the vessel at the time of the TEST shall be detailed as follows:

- The heading of the vessel shall be expressed in degrees between 0 to 359 and shall be preceded by the words "Heading", "HDG", "Course" or "COG" and may be written in uppercase, lowercase or a combination of both .
- The speed of the ship shall be expressed in knots and shall be preceded by the words "Speed", "SOG" or "Spd" and then indicate one of the following terms "knots", "knts", "kn" or " kt "and may be written in uppercase, lowercase or a combination of both.

TEST indicators should contain:

- **Messages must include the word "TEST ". (The Word TEST at least once.)**
- In case the message received does not contain the words "TEST", the Panama Maritime Authority will request confirmation to the CSO about the status of the ship, the crew and thus, in this way rule out any case of false alarm. **(For those ships that have already made the TEST, it is completely valid).**

We request all CSO to verify the information that appears on the SSAS platform and update their data. In case the indicated company is not the one that appears in the last DOC please send an email to info@panama-ssas.com for its update.

CONFIRMATION MESSAGE OF THE ANNUAL SSAS TEST

SUSCCEFUL TEST when:

1. The Maritime Ships Security Department confirms the reception of the same in the date scheduled in the Electronic Platform.
2. The TEST message includes all the information described in this Merchant Marine Circular.
3. The general ship data such as: name, IMO number, call signs and MMSI numbers are correct, as are the geographic coordinates and date received.

FAILED TEST: In the event that the test does not comply with the information above and shall be re-scheduled through the SSAS platform in accordance with what is established in the fifth paragraph of this Resolution.

PENDING TEST: In the event that the SSAS TEST cannot be carried out, and this must be notified by email to the

account info@panama-ssas.com 24 hours in advance, the reasons and the new date of programming through the SSAS platform.

In cases where the SSAS TEST cannot be performed due to technical problems of the equipment, it should be communicated to the email: info@panama-ssas.com.

For more information about these new regulations and check the compatibility of the equipment please send an email to info@panama-ssas.com.

12. Special instructions in HRA

1. The PMA recommends that all Panamanian Flagged vessels with or without armed or unarmed security personnel, and that prior to the entry into the High Risk Area (HRA), the crew should be fully briefed on the preparations and a piracy drill shall be conducted as well. The security drill should be reviewed and all personnel briefed on their duties, including familiarization with the alarm using to identify a piracy attack.
2. These drills must to schedule through the SSAS platform in following link: <https://polestarglobal.force.com/SSAS/login>, indicating that it is a “Piracy Drill” or “SSAS Test”, at the same time the Panamanian Flagged vessels are requested to verify that the SSAS equipment have been correctly set-up and is working properly.
3. These measures should be taken to ensure that the security procedures are working properly along with the recommendations stated in the Best Management Practices **BMP (last version)** and the Internationally Recommended Transit Corridor (IRTC) established in the Merchant Marine Circulars No. 208 and No.238.
4. In case that the message received indicates the words **SSAS ALERT** or **SECURITY**, the PMA will require a confirmation about the status of the ship and the crew.

For the vessels that have been granted a Certificate of Exemption from the use of the SSAS or they are out of service during a calendar year and have a Certificate of Special Registry of Laid-Up are excluded of the present Resolution.

In cases of noncompliance with these regulations the Panama Maritime Authority may impose the following sanctions:

- The International Ship Security Certificate (ISSC) may be invalidated y/o will not be issued.
- Additional audits of the ISPS Code may be authorized to vessels that demonstrate non-compliance with the provisions of this Resolution.

For further assistance and/or inquiries please note the following contact points:

A. Maritime Ships Security Department

Phone: +507-501-5037/5085

E-mail address: threat@amp.gob.pa / info@panama-ssas.com

B. SEGUMAR Panama (Evenings, Weekends and Holidays)

Phone: +507-501-5350/48 or +507-501-5032

E-mail address: authorizations@segumar.com

January 2019 – Modification of paragraphs from 1, 2, 3, 4 and 12, inclusion of paragraphs from 5 to 11 and exclusion of paragraphs 9 to 21 and posted in MMC-125

November 2018 – Modification of paragraph s NEW REGULATIONS FOR SSAS TEST MESSAGE AND ANNUAL SSAS TEST MESSAGE

April 2018 - Modification of TEST Message (Test indicators) and SSAS MALFUNCTIONING

March 2018- Modification of TEST Message (Test indicators)

January 2018 – Modification of paragraph s NEW REGULATIONS FOR SSAS TEST MESSAGE AND ANNUAL SSAS TEST MESSAGE

October 2017- Inclusion of paragraphs 2 and 3 in the New Regulations for SSAS TEST MESSAGE

October 2017 - Inclusion of Resolution No.106-107-DGMM (English version)

October 2017 – Changes all throughout the text

March 2016 – Change in paragraph 6

January 2016 – Changes throughout the text

October 2015- Changes in paragraph 12 and 13

August, 2014 – Changes throughout the text

September, 2013 - Changes in paragraph 7

June, 2013 - Changes in paragraph 12

May,2013 – New points 11 and 12

March, 2012 - Changes all throughout the text

February, 2004-First issuance

Inquiries concerning the subject of this Circular or any other request should be directed to:

Maritime Ships Security Department.

Directorate General of Merchant Marine

Panama Maritime Authority

Phones: (507) 501-5037 / 501-5085

E-mail: isps@amp.gob.pa